

## General Information

Date & Time: 24, Feb, 2026 15:17

<b>Make</b>	Toyota	<b>Model</b>	Lite Ace
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	146,045
<b>Registration No.</b>	DBG5408	<b>Chassis No.</b>	MHKB3FE10NK001090
<b>CC</b>	1.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Van
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	61.0	60	69	55
2	Boot Lid	52.2	44	65	48
3	Roof	57.8	78	46	54/53
4	Left Front Fender	58.6	61	51	64
5	Left Front Door	55.4	59	57	50
6	Center Panel Left				
7	Left Rear Door	53.8	52	54	56
8	Left Back Panel	56.2	53	59	57
9	Right Front Fender	55.2	56	51	59
10	Right Front Door	49.7	49	50	50
11	Center Panel Right				
12	Right Rear Door	54.6	57	54	53
13	Right Back Panel	57.4	52	51	70

**Overall Evaluation :**

D

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	D	<b>Exterior Evaluation :</b>	E
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / Ceiling - Grime - Large / Trim Other - Worked - Large / Trim Other - Worked - Large / Trunk Room - Worn, Scratch, Cut, Crack - Large / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / (L) Front Trim - Grime - Medium / Console, Switches, Vents - Traces of Adhesive Tape - Yes</p>		<p><b>Remarks</b> (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Rear Fender, Molding - Scratch &amp; Dent - Medium / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / Rear Windshield - Damaged - Large / Trunk Hood, Rear Gate - Scratch &amp; Dent - Large / (L) Rear Fender, Molding - Scratch &amp; Dent - Large / (L) Rear Door, Molding - Scratch &amp; Dent - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Front Panel - Rust, Corrosion - Small / Roof - Scratch - Small / Front Windshield - Scratch, Stone chip - Small</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	C
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Warning Lamps - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes</p>	

<b>Inspector Notes</b>
with warranty booklet, no jack and tools, with spare tire, with LTO plate, scratched and cracked tail light, plate and park light issue, check engine warning lamp ON, traction control indicator ON,