

General Information

Date & Time: 24, Feb, 2026 12:26

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	32,333
Registration No.	DBP8768	Chassis No.	PA1B18F35R4266811
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.1	109	96	101
2	Boot Lid	114.3	111	114	118
3	Roof	98.7	105	99	101/90
4	Left Front Fender	99.6	98	101	100
5	Left Front Door	101.3	100	100	104
6	Center Panel Left				
7	Left Rear Door	106.3	113	101	105
8	Left Back Panel	114.0	120	110	112
9	Right Front Fender	105.4	99	111	106
10	Right Front Door	97.2	93	99	99
11	Center Panel Right				
12	Right Rear Door	96.8	96	97	98
13	Right Back Panel	105.6	105	99	113

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Cut, Crack - Medium / (L) Front Floor Mat - Worked - Large / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Floor Mat - Grime - Medium / Ceiling - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Dent - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack and tools, no spare tire, with LTO plate, scratches on tail light</p>