

General Information

Date & Time: 24, Feb, 2026 16:58

Make	Toyota	Model	Fortuner
YOM	2025	Odo Meter Reading	15,006
Registration No.	DBT3438	Chassis No.	MHFCB3GS7R0498182
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	124	111	98
2	Boot Lid	102.0	96	116	94
3	Roof	114.0	121	139	94/102
4	Left Front Fender	115.3	124	112	110
5	Left Front Door	117.6	123	121	109
6	Center Panel Left				
7	Left Rear Door	109.0	114	111	102
8	Left Back Panel	116.3	103	122	124
9	Right Front Fender	105.3	115	100	101
10	Right Front Door	104.6	97	109	108
11	Center Panel Right				
12	Right Rear Door	101.6	101	101	103
13	Right Back Panel	127.6	154	108	121

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small / Ceiling - Grime - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Medium</p>	<p>Remarks (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>with LTO plate, with warranty and manual booklet, with reverse camera, with spare tire, with jack and tools, with spare key, scratches on taillight and headlight.</p>