

General Information

Date & Time: 23, Feb, 2026 12:08

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	34,849
Registration No.	NGX2546-1	Chassis No.	PA1B18F38N4170049
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	112	109	113
2	Boot Lid	106.3	104	104	111
3	Roof	97.2	106	90	93/101
4	Left Front Fender	91.4	96	93	85
5	Left Front Door	108.0	104	119	101
6	Center Panel Left				
7	Left Rear Door	104.0	105	101	106
8	Left Back Panel	105.6	108	100	109
9	Right Front Fender	90.8	88	90	95
10	Right Front Door	117.3	115	115	122
11	Center Panel Right				
12	Right Rear Door	95.9	90	93	105
13	Right Back Panel	106.6	104	100	116

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p>Remarks (L) Rear Door, Molding - Dent - Large / (R) Front Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Crack, Gap - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Medium / (R) Front Fender, Molding - Crack, Gap - Large / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet/ no tools/ possible flooding/ no sparetire/ with jack/ with LTO plate</p>