

General Information

Date & Time: 04, Feb, 2025 13:39

Make	Toyota	Model	Hilux
YOM	2023	Mileage	45,698
Registration No.	NIU6260	Chassis No.	MR0AB8DDXP5036139
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	90.5	93	90	89
2	Boot Lid	89.1	82	82	103
3	Roof	127.5	109	109	165/127
4	Left Front Fender	118.6	124	119	113
5	Left Front Door	111.0	113	112	108
6	Center Panel Left	87.3	90	75	98
7	Left Rear Door	106.6	109	107	104
8	Left Back Panel	112.6	112	111	115
9	Right Front Fender	161.0	160	159	164
10	Right Front Door	130.3	171	111	109
11	Center Panel Right	127.0	125	114	142
12	Right Rear Door	111.3	105	105	124
13	Right Back Panel	109.3	107	116	105

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Missing - Yes / (L) Front Seat - Grime - Small	Remarks Bonnet - Repair Traces - Yes / (L) Rear Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Dent - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / Roof - Scratch & Dent - Medium / Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate number/with warranty booklet/No jack and tools/noisy rear brake/ adhesive mark on front windshield/ no spare tire