

General Information

Date & Time: 21, Feb, 2026 16:38

Make	Toyota	Model	Hilux
YOM	2023	Odo Meter Reading	50,297
Registration No.	NHJ7202	Chassis No.	MR0AB8DDXP5147970
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.0	119	128	122
2	Boot Lid	230.0	378	154	158
3	Roof	122.0	117	105	151/115
4	Left Front Fender	107.0	110	104	107
5	Left Front Door	117.6	116	121	116
6	Center Panel Left				
7	Left Rear Door	105.9	115	103	100
8	Left Back Panel	118.0	105	116	133
9	Right Front Fender	107.0	106	108	107
10	Right Front Door	106.0	109	106	103
11	Center Panel Right				
12	Right Rear Door	211.3	138	375	121
13	Right Back Panel	114.0	113	116	113

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Small</p>	<p>Remarks (R) Step - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Rear Gate - Repair mark - Yes / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Large / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (L) Side Gate - Scratch - Medium / (R) Side Gate - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no jack and tools/ with spare tire and LTO plate/ with warranty booklet/</p>