

General Information

Date & Time: 23, Feb, 2026 10:35

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	48,017
Registration No.	NHS8466	Chassis No.	PA1B18F39R4271154
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.3	115	114	120
2	Boot Lid	114.6	111	120	113
3	Roof	103.1	112	100	100/101
4	Left Front Fender	97.4	106	94	93
5	Left Front Door	104.6	104	100	110
6	Center Panel Left				
7	Left Rear Door	104.6	111	103	100
8	Left Back Panel	112.3	118	112	107
9	Right Front Fender	100.6	99	102	101
10	Right Front Door	100.6	100	101	101
11	Center Panel Right				
12	Right Rear Door	106.0	103	101	114
13	Right Back Panel	111.3	108	104	122

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Large / (L) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Large</p>	<p>Remarks Bonnet, Headlight - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet/ with jack and spare tire/ with LTO plate/ with tools/</p>