

## General Information

Date & Time: 23, Feb, 2026 16:03

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	21,121
<b>Registration No.</b>	BAG2864	<b>Chassis No.</b>	PA1B18F34R4255167
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	112	111	113
2	Boot Lid	112.3	122	104	111
3	Roof	109.4	96	111	110/121
4	Left Front Fender	112.6	115	120	103
5	Left Front Door	109.0	118	107	102
6	Center Panel Left				
7	Left Rear Door	114.6	108	122	114
8	Left Back Panel	108.0	109	109	106
9	Right Front Fender	109.0	110	106	111
10	Right Front Door	112.0	111	110	115
11	Center Panel Right				
12	Right Rear Door	109.3	111	107	110
13	Right Back Panel	109.3	113	109	106

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Floor Mat - Missing - Yes / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Medium</p>	<p><b>Remarks</b> Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch - Large / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>no tools/ with jack and spare tire/ with warranty booklet and LTO plate/</p>