

General Information

Date & Time: 21, Feb, 2026 18:06

Make	Suzuki	Model	Dzire
YOM	2024	Odo Meter Reading	20,564
Registration No.	NFF9387	Chassis No.	MBHZF63S6RG470764
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.6	104	106	104
2	Boot Lid	81.0	85	85	73
3	Roof	103.8	95	98	106/116
4	Left Front Fender	98.1	101	100	94
5	Left Front Door	97.3	100	96	96
6	Center Panel Left				
7	Left Rear Door	89.1	98	90	80
8	Left Back Panel	95.2	98	103	85
9	Right Front Fender	96.4	97	99	94
10	Right Front Door	99.0	96	98	104
11	Center Panel Right				
12	Right Rear Door	91.9	94	91	91
13	Right Back Panel	101.6	94	101	110

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Smell - Yes / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Trim - Grime - Medium / (R) Front Seat - Grime - Large / Rear Seat - Grime - Large / (L) Front Floor Mat - Worked - Large / (L) Front Seat - Grime - Medium</p>	<p>Remarks Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Crack, Gap - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Large / Roof - Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>no jack and tools/ no spare tire/ with LTO plate and warranty booklet/</p>