

General Information

Date & Time: 23, Feb, 2026 15:35

Make	Toyota	Model	Hiace
YOM	2024	Odo Meter Reading	20,309
Registration No.	CBI9561	Chassis No.	JTFNAFAPXP8035777
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.6	110	108	108
2	Boot Lid	100.3	99	100	102
3	Roof	105.2	100	119	99/103
4	Left Front Fender	104.6	107	104	103
5	Left Front Door	107.0	118	105	98
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	97.5	93	96	103
9	Right Front Fender	109.3	105	106	117
10	Right Front Door	106.0	102	105	111
11	Center Panel Right	115.3	117	115	114
12	Right Rear Door	108.3	106	106	113
13	Right Back Panel	102.3	101	106	100

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Ceiling - Grime - Large / (L) Front Floor Mat - Worked - Large</p>		<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Center Panel - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Crack, Gap - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
no tools and jack/ with LTO plate and warranty booklet/ with spare tire/