

General Information

Date & Time: 21, Feb, 2026 16:37

Make	Toyota	Model	Vios
YOM	2026	Odo Meter Reading	5,501
Registration No.	CCQ5021	Chassis No.	PA1B18F37S4297371
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	123	110	110
2	Boot Lid	113.6	111	112	118
3	Roof	107.2	109	107	105/108
4	Left Front Fender	102.0	105	101	100
5	Left Front Door	107.6	110	109	104
6	Center Panel Left				
7	Left Rear Door	108.0	106	108	110
8	Left Back Panel	111.3	108	110	116
9	Right Front Fender	105.6	103	105	109
10	Right Front Door	117.3	113	121	118
11	Center Panel Right				
12	Right Rear Door	110.6	115	107	110
13	Right Back Panel	119.3	115	110	133

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Medium</p>	<p>Remarks (L) Front Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

Inspector Notes

no tools/ with jack and spare tire/ with LTO plate and warranty booklet/