

## General Information

Date & Time: 23, Feb, 2026 10:17

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	114,266
<b>Registration No.</b>	NIN5353	<b>Chassis No.</b>	PA1B18F37P4209555
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	106	113	122
2	Boot Lid	121.6	113	133	119
3	Roof	107.8	111	98	106/116
4	Left Front Fender	144.3	142	139	152
5	Left Front Door	523.6	1,264	157	150
6	Center Panel Left				
7	Left Rear Door	111.3	124	110	100
8	Left Back Panel	124.3	121	118	134
9	Right Front Fender	102.1	103	104	100
10	Right Front Door	101.6	104	100	101
11	Center Panel Right				
12	Right Rear Door	110.0	105	103	122
13	Right Back Panel	101.6	96	99	110

Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>  Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Small / Ceiling - Crinkle - Medium / Dashboard - Worked - Minimal / Instrument Panel - Worn, Scratch, Cut, Crack - Medium</p>	<p><b>Remarks</b>  (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Front Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch &amp; Dent - Medium / (L) Rear Door, Molding - Scratch &amp; Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / (L) Rear Fender, Molding - Scratch &amp; Dent - Medium / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / (R) Rear Fender, Molding - Modified - Medium / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / (R) Front Fender, Molding - Scratch &amp; Dent - Large / Bonnet, Headlight - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Medium / (L) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Roof - Scratch &amp; Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b>  Left Front Pillar - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Pillar - Condition of Welding ? - Yes</p>	<p><b>Remarks</b>  Warning Lamps - Issue - Yes</p>

<p><b>Inspector Notes</b></p>
<p>No LTO plate, with spare tire, no spare key, no warranty and manual booklet, no jack and tools, check engine lamp indicator, issue on driver side door, scratches on taillight and headlight, plate light issue.</p>