

General Information

Date & Time: 23, Feb, 2026 16:00

Make	Toyota	Model	Hiace
YOM	2023	Odo Meter Reading	68,705
Registration No.	CBT8990	Chassis No.	JTFJT02P5P5033425
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Vehicle
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.6	130	133	126
2	Boot Lid	125.0	124	129	122
3	Roof	194.7	161	110	397/111
4	Left Front Fender	132.6	128	138	132
5	Left Front Door	124.6	132	122	120
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	122.6	124	118	126
9	Right Front Fender	139.3	140	146	132
10	Right Front Door	123.6	122	123	126
11	Center Panel Right	134.6	159	123	122
12	Right Rear Door	133.0	139	130	130
13	Right Back Panel	131.0	135	122	136

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Dashboard - Worked - Minimal / Glove Box - Worked - Minimal / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Medium / Rear Seat - Grime - Small / Ceiling - Grime - Small / (L) Front Floor Mat - Grime - Medium	Remarks Roof - Repair Traces - Yes / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Center Panel - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / Front Panel - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Roof - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, with spare tire, no spare key, no warranty and manual booklet, scratches on taillight and headlight, no reverse camera, issue on rear seat.