

## General Information

Date & Time: 23, Feb, 2026 10:55

<b>Make</b>	Toyota	<b>Model</b>	Wigo
<b>YOM</b>	2021	<b>Odo Meter Reading</b>	36,504
<b>Registration No.</b>	CBM3688	<b>Chassis No.</b>	MHKA4DF5FMJ054724
<b>CC</b>	1.0	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Hatchback
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	166.3	136	163	200
2	Boot Lid	88.7	83	94	90
3	Roof	348.5	320	799	147/128
4	Left Front Fender	618.6	951	243	662
5	Left Front Door	287.0	178	131	552
6	Center Panel Left				
7	Left Rear Door	352.3	766	135	156
8	Left Back Panel	359.3	359	465	254
9	Right Front Fender	303.6	156	227	528
10	Right Front Door	219.0	152	185	320
11	Center Panel Right				
12	Right Rear Door	174.6	162	140	222
13	Right Back Panel	522.6	136	178	1,254

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

