

General Information

Date & Time: 25, Feb, 2026 12:43

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	35,396
Registration No.	NFC7502	Chassis No.	PA1B18F38P4222508
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	116	103	115
2	Boot Lid	112.3	103	117	117
3	Roof	108.5	106	100	127/101
4	Left Front Fender	113.0	118	119	102
5	Left Front Door	101.8	105	102	99
6	Center Panel Left				
7	Left Rear Door	103.6	111	100	100
8	Left Back Panel	119.6	131	120	108
9	Right Front Fender	104.6	109	103	102
10	Right Front Door	103.3	109	99	102
11	Center Panel Right				
12	Right Rear Door	87.1	89	82	90
13	Right Back Panel	144.3	144	143	146

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Carpet - Worked - Large / (R) Rear Trim - Grime - Minimal / (R) Front Seat - Worn - Yes / (L) Front Seat - Worn - Yes / Rear Seat - Grime - Large / Dashboard - Loose, Deformed - Medium / Knobs - Worn, Peel, Crack - Small / (L) Front Trim - Grime - Minimal</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : D
<p>Remarks Defects not found</p>	<p>Remarks Warning Lamps - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with jack, with spare tire, scratches on tail lights, no tools, ABS warning lamp on, traction control warning lamp on</p>