

General Information

Date & Time: 23, Feb, 2026 11:47

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	15,011
Registration No.	FAT1857	Chassis No.	PA1B18F31S4286611
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	92.7	90	92	96
2	Boot Lid	97.0	93	94	104
3	Roof	85.1	88	91	79/83
4	Left Front Fender	82.2	82	83	83
5	Left Front Door	84.2	83	89	81
6	Center Panel Left				
7	Left Rear Door	86.2	85	85	89
8	Left Back Panel	87.7	95	86	82
9	Right Front Fender	87.5	88	88	87
10	Right Front Door	88.8	92	91	84
11	Center Panel Right				
12	Right Rear Door	90.7	86	89	98
13	Right Back Panel	93.2	91	89	100

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Small / (L) Front Seat - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Rear Trim - Grime - Small / Rear Seat - Grime - Small</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Fender, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>No warranty booklet. No Seat cover. With Spare Tire. No spare key. No Jack and tools</p>