

General Information

Date & Time: 24, Feb, 2026 08:26

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	33,999
Registration No.	NJC8411	Chassis No.	PAHACACA2S6425666
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.5	99	101	102
2	Boot Lid	60.2	86	50	45
3	Roof	129.7	162	123	111/123
4	Left Front Fender	99.7	105	102	92
5	Left Front Door	98.6	100	100	96
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	77.2	73	84	75
9	Right Front Fender	100.5	98	105	99
10	Right Front Door	100.2	94	101	106
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	67.3	58	77	67

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Ceiling - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks Roof - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Guard Frame - Scratch - Large / Cargo Bed Floor - Scratch & Dent - Large / Rear Gate - Scratch & Dent - Medium / Roof - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Guard Frame - Scratch - Small / Roof - Repair mark - Yes</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with 1 spare key/with jack and tools/No seat cover/No reverse camera/No fog light/with warranty booklet</p>