

General Information

Date & Time: 23, Feb, 2026 13:00

Make	Toyota	Model	Hilux
YOM	2022	Odo Meter Reading	75,191
Registration No.	FAO3213	Chassis No.	MR0CB8CB4N4290067
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.6	100	114	100
2	Boot Lid	157.6	162	138	173
3	Roof				
4	Left Front Fender	88.7	91	84	91
5	Left Front Door	98.4	91	104	100
6	Center Panel Left	114.6	115	106	123
7	Left Rear Door				
8	Left Back Panel	167.0	154	212	135
9	Right Front Fender	87.1	85	92	85
10	Right Front Door	94.3	99	96	88
11	Center Panel Right	127.3	123	138	121
12	Right Rear Door				
13	Right Back Panel	124.0	106	119	147

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Large / Dashboard - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks Bonnet - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Small / (R) Side Gate - Scratch - Medium / Rear Gate - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>With Spare tire, with warranty booklet, with 2 Spare keys. no jack and tools. no seat cover</p>