

## General Information

Date & Time: 23, Feb, 2026 14:48

<b>Make</b>	Toyota	<b>Model</b>	Wigo
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	46,432
<b>Registration No.</b>	FAQ4931	<b>Chassis No.</b>	MHKAA1BC7PJ008959
<b>CC</b>	1.0	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Hatchback
<b>Colour</b>	Yellow		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	108	110	110
2	Boot Lid	84.3	84	89	80
3	Roof	84.3	81	93	81/84
4	Left Front Fender	90.9	93	87	93
5	Left Front Door	103.0	101	102	106
6	Center Panel Left				
7	Left Rear Door	96.7	105	91	94
8	Left Back Panel	86.8	93	84	83
9	Right Front Fender	101.2	111	102	91
10	Right Front Door	101.1	104	100	100
11	Center Panel Right				
12	Right Rear Door	93.3	85	91	104
13	Right Back Panel	90.8	86	87	100

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>B</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Ceiling - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small	<b>Remarks</b> (R) Front Door, Molding - Scratch - Small / (L) Front Door, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Mirror - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>C</b></span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Power Steering - Issue - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist

<b>Inspector Notes</b>
not stock horn. with spare tire. no spare key. no seatcover. no warranty booklet