

General Information

Date & Time: 02, Mar, 2026 08:24

Make	Toyota	Model	Lite Ace
YOM	2025	Odo Meter Reading	26,870
Registration No.	HAH4931	Chassis No.	MHKB3FE10RK004392
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Commercial Vehicles
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	60.8	62	61	59
2	Boot Lid	58.9	55	74	48
3	Roof	55.1	61	52	53/54
4	Left Front Fender	63.7	57	63	71
5	Left Front Door	59.5	62	60	57
6	Center Panel Left				
7	Left Rear Door	59.3	59	60	59
8	Left Back Panel	66.6	72	60	68
9	Right Front Fender	59.5	70	56	53
10	Right Front Door	59.3	67	55	56
11	Center Panel Right				
12	Right Rear Door	59.9	57	64	59
13	Right Back Panel	62.1	66	62	59

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Mat Other - Grime - Large / Ceiling - Grime - Large / (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / Display, Audio System - Partially Missing - Yes / Carpet - Worked - Large</p>	<p>Remarks (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Medium / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

Inspector Notes

With warranty booklet, spare tire, jack. and tools. Incomplete seat. cover. 2 keys. With LTO plate..