

General Information

Date & Time: 24, Feb, 2026 17:22

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	59,917
Registration No.	HAH2478	Chassis No.	PA1B18F36R4241576
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	110	104	113
2	Boot Lid	105.6	103	102	112
3	Roof	102.9	95	113	104/100
4	Left Front Fender	94.8	94	93	98
5	Left Front Door	99.3	102	99	97
6	Center Panel Left				
7	Left Rear Door	108.6	112	110	104
8	Left Back Panel	111.0	113	112	108
9	Right Front Fender	164.3	247	127	119
10	Right Front Door	101.6	102	102	101
11	Center Panel Right				
12	Right Rear Door	105.1	100	99	117
13	Right Back Panel	112.3	111	109	117

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Large / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / Overall Interior - Animal Hair - Yes / Sunvisor, Sunglass Holder - Grime - Small / Ceiling - Grime - Small / Rear Seat - Grime - Large / Mat Other - Grime - Large / (R) Rear Trim - Grime - Small / (R) Front Trim - Grime - Medium / (R) Front Floor Mat - Grime - Large / (R) Front Seat - Grime - Large</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Mirror - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Medium / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

Inspector Notes
<p>Possible flooding. Gap at front bumper. Gap at bonnet and grille. Top grille loose. Front emblem missing. Without warranty booklet and tools. Incomplete seat cover. With spare tire and jack. 1 key. With LTO plate.</p>