

General Information

Date & Time: 25, Feb, 2026 15:55

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	47,163
Registration No.	DBS1487	Chassis No.	PA1B18F32R4279628
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.6	115	105	100
2	Boot Lid	106.3	105	107	107
3	Roof	101.9	101	107	103/97
4	Left Front Fender	98.4	100	100	95
5	Left Front Door	101.8	99	105	102
6	Center Panel Left				
7	Left Rear Door	104.0	103	101	108
8	Left Back Panel	102.5	108	98	102
9	Right Front Fender	102.3	100	104	103
10	Right Front Door	105.0	110	105	100
11	Center Panel Right				
12	Right Rear Door	107.6	105	106	112
13	Right Back Panel	103.6	101	102	108

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Cut, Crack - Medium / Ceiling - Grime - Small / (R) Front Trim - Grime - Minimal / Rear Seat - Grime - Large / (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes / (L) Front Trim - Grime - Small / (L) Rear Trim - Cut, Crack - Minimal</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Crack - Damaged / (R) Rear Door, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Retractable Mirror - Issue - Yes / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with jack, no warranty booklet, no spare tire, no tools, scratches on headlights and tail lights, head unit issu</p>