

General Information

Date & Time: 02, Feb, 2025 11:00

Make	Toyota	Model	Vios
YOM	2022	Mileage	59,810
Registration No.	NFE1013	Chassis No.	PA1B18F35N4180148
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.6	110	133	116
2	Boot Lid	147.0	137	141	163
3	Roof	100.5	108	93	105/96
4	Left Front Fender	103.6	103	102	106
5	Left Front Door	102.6	107	103	98
6	Center Panel Left				
7	Left Rear Door	101.6	102	104	99
8	Left Back Panel	112.0	120	106	110
9	Right Front Fender	100.6	104	100	98
10	Right Front Door	103.3	104	106	100
11	Center Panel Right				
12	Right Rear Door	110.0	103	109	118
13	Right Back Panel	141.0	138	128	157

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Step, In-panel, Side Spoiler - Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Trunk Hood, Rear Gate - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with LTO plate numbermber/spare tire/jack/No reverse camera/No warranty booklet/leather seat cover/ worn tires