

General Information

Date & Time: 24, Feb, 2026 13:54

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	31,659
Registration No.	GBC9126	Chassis No.	PA1B18F35R4239432
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.3	107	103	103
2	Boot Lid	106.2	106	99	114
3	Roof	95.8	100	102	87/95
4	Left Front Fender	92.3	92	89	96
5	Left Front Door	92.2	94	92	90
6	Center Panel Left				
7	Left Rear Door	95.8	100	95	93
8	Left Back Panel	99.3	109	99	90
9	Right Front Fender	95.4	99	94	93
10	Right Front Door	92.8	94	88	98
11	Center Panel Right				
12	Right Rear Door	100.6	92	95	115
13	Right Back Panel	362.3	440	475	172

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Minimal</p>	<p>Remarks (R) Rear Fender - Repair Traces - Yes / (R) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / Roof - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

Inspector Notes
No remote key. With Spare tire. no jack and tools. no warranty booklet. no seat cover