

## General Information

Date & Time: 25, Feb, 2026 15:52

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	23,270
<b>Registration No.</b>	NHU6482	<b>Chassis No.</b>	PA1B18F38R4270092
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>116.0</b>	116	108	124
2	Boot Lid	<b>121.0</b>	124	108	131
3	Roof	<b>114.5</b>	110	125	110/113
4	Left Front Fender	<b>111.6</b>	117	111	107
5	Left Front Door	<b>111.0</b>	112	114	107
6	Center Panel Left				
7	Left Rear Door	<b>115.0</b>	119	116	110
8	Left Back Panel	<b>117.0</b>	124	118	109
9	Right Front Fender	<b>114.3</b>	111	110	122
10	Right Front Door	<b>115.0</b>	112	118	115
11	Center Panel Right				
12	Right Rear Door	<b>118.3</b>	126	111	118
13	Right Back Panel	<b>122.6</b>	114	135	119

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

