

General Information

Date & Time: 02, Mar, 2026 12:48

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	11,779
Registration No.	NKH6389	Chassis No.	MHFAB1BY0R3122283
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	108	109	113
2	Boot Lid	112.3	141	109	87
3	Roof	114.2	129	117	108/103
4	Left Front Fender	104.6	111	102	101
5	Left Front Door	122.0	109	124	133
6	Center Panel Left				
7	Left Rear Door	115.3	118	108	120
8	Left Back Panel	122.0	135	109	122
9	Right Front Fender	102.3	109	102	96
10	Right Front Door	110.3	116	112	103
11	Center Panel Right				
12	Right Rear Door	110.0	113	106	111
13	Right Back Panel	120.6	130	111	121

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Medium / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with 1 spare key/No seat cover/with jack No tools/with reverse camera/with warranty booklet/</p>