

General Information

Date & Time: 02, Mar, 2026 15:29

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	38,342
Registration No.	CAZ8311	Chassis No.	PA1B18F34P4237149
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	140.6	163	113	146
2	Boot Lid	120.6	104	116	142
3	Roof	109.1	106	129	100/102
4	Left Front Fender	123.6	143	121	107
5	Left Front Door	130.6	138	134	120
6	Center Panel Left				
7	Left Rear Door	116.3	109	105	135
8	Left Back Panel	108.3	119	105	101
9	Right Front Fender	102.3	103	101	103
10	Right Front Door	106.6	108	105	107
11	Center Panel Right				
12	Right Rear Door	106.9	96	102	123
13	Right Back Panel	163.6	159	163	169

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Large / (L) Front Floor Mat - Worked - Large / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Rear Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (R) Front Seat Head Rest - Worked - Small / (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate, with spare tire, with warranty booklet, with jack and tools, scratches on headlight and taillights</p>