

General Information

Date & Time: 02, Mar, 2026 15:35

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	10,975
Registration No.	DBR2385	Chassis No.	MHKAA1BC9RJ025958
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.6	104	112	119
2	Boot Lid	95.7	104	102	81
3	Roof	92.8	89	78	90/115
4	Left Front Fender	86.6	84	94	82
5	Left Front Door	113.3	107	108	125
6	Center Panel Left				
7	Left Rear Door	102.1	105	99	103
8	Left Back Panel	98.3	102	100	93
9	Right Front Fender	85.5	89	80	87
10	Right Front Door	97.4	103	90	99
11	Center Panel Right				
12	Right Rear Door	100.2	100	95	106
13	Right Back Panel	96.2	100	102	87

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (L) Front Floor Mat - Worked - Large / (L) Front Seat - Grime - Medium</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Door, Molding - Dent - Small / (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet/ no tools/ no jack / with LTO plate and sparetire/</p>