

General Information

Date & Time: 01, Feb, 2025 15:54

Make	Toyota	Model	Vios
YOM	2017	Mileage	71,175
Registration No.	NCN6760	Chassis No.	PA1B19F32H402504E
CC	1.3	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	111	123	107
2	Boot Lid	151.6	121	200	134
3	Roof	114.0	105	111	110/130
4	Left Front Fender	115.3	113	117	116
5	Left Front Door	115.6	124	122	101
6	Center Panel Left				
7	Left Rear Door	136.6	149	129	132
8	Left Back Panel	135.3	137	135	134
9	Right Front Fender	118.0	119	119	116
10	Right Front Door	119.0	108	122	127
11	Center Panel Right				
12	Right Rear Door	116.3	132	113	104
13	Right Back Panel	121.6	127	104	134

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Loose, Deformed - Large / (L) Front Floor Mat - Worked - Large / (R) Front Floor Mat - Missing - Yes / Ceiling - Crinkle - Medium	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Dent - Small / Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Repair mark - Difference in Color / (L) Rear Door, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Crack, Gap - Small / Bonnet, Headlight - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Air Conditioner - Function - Weak / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, with spare and tools, with jack, with LTO plate, yellowish headlight, front right headlight burnt mark, steering control not working, backseat cover issue, reverse camera not working