

General Information

Date & Time: 02, Mar, 2026 10:58

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	6,943
Registration No.	DBU8831	Chassis No.	MHKAA1BC4SJ038560
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	108	112	121
2	Boot Lid	95.9	93	103	92
3	Roof	100.9	105	99	102/98
4	Left Front Fender	103.6	104	105	102
5	Left Front Door	106.3	112	102	105
6	Center Panel Left				
7	Left Rear Door	104.1	108	99	105
8	Left Back Panel	98.4	92	96	107
9	Right Front Fender	106.3	99	111	109
10	Right Front Door	104.6	106	101	107
11	Center Panel Right				
12	Right Rear Door	105.0	109	100	106
13	Right Back Panel	101.8	97	108	101

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / Ceiling - Grime - Medium</p>	<p>Remarks (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>No LTO plate/with spare tire/with 1 spare key /No seat cover /with jack No tools/with warranty booklet/with reverse camera</p>