

General Information

Date & Time: 25, Feb, 2026 15:56

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	53,223
Registration No.	NHS8801	Chassis No.	PA1B18F38R4268763
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	107	106	128
2	Boot Lid	124.3	127	122	124
3	Roof	113.2	124	109	109/111
4	Left Front Fender	117.0	114	129	108
5	Left Front Door	112.3	107	106	124
6	Center Panel Left				
7	Left Rear Door	112.3	116	111	110
8	Left Back Panel	114.0	117	113	112
9	Right Front Fender	113.3	112	114	114
10	Right Front Door	112.3	115	111	111
11	Center Panel Right				
12	Right Rear Door	116.6	108	113	129
13	Right Back Panel	110.6	112	108	112

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Medium / (L) Rear Trim - Loose, Deformed - Medium / (R) Front Trim - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Minimal / (L) Front Floor Mat - Cut, Crack - Medium / (R) Front Floor Mat - Grime - Small</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / Roof - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>with LTO plate, with spare tire, with jack & inc tools, with manual and warranty booklet, with spare key, scratches on taillight and headlight.</p>