

General Information

Date & Time: 04, Feb, 2025 08:59

Make	Toyota	Model	Vios
YOM	2023	Mileage	21,713
Registration No.	NHB6725	Chassis No.	PA1B18F33N4192735
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	114	105	117
2	Boot Lid	104.3	103	103	107
3	Roof	93.4	96	88	95/96
4	Left Front Fender	205.6	294	191	132
5	Left Front Door	106.3	107	113	99
6	Center Panel Left				
7	Left Rear Door	100.7	105	100	97
8	Left Back Panel	105.4	113	105	98
9	Right Front Fender	99.5	101	99	99
10	Right Front Door	108.6	123	101	102
11	Center Panel Right				
12	Right Rear Door	98.9	92	95	110
13	Right Back Panel	98.5	92	98	106

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (L) Front Floor Mat - Grime - Small	Remarks (L) Front Fender - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Fender, Molding - Dent - Small / (R) Rear Door, Molding - Dent - Minimal / Roof - Dent - Small / Trunk Hood, Rear Gate - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes

with LTO plate number/spare tire/jack/warranty booklet/No reverse camera/No tools