

General Information

Date & Time: 27, Feb, 2026 10:24

Make	Toyota	Model	Yaris Cross
YOM	2024	Odo Meter Reading	15,644
Registration No.	NNV9637	Chassis No.	MHFAB8BF9P0012855
CC	1.5	Transmission	CVT
Fuel Type	Hybrid	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	149.3	144	169	135
2	Boot Lid	135.6	132	140	135
3	Roof	121.2	139	139	101/106
4	Left Front Fender	144.0	134	145	153
5	Left Front Door	238.3	220	236	259
6	Center Panel Left				
7	Left Rear Door	249.0	252	224	271
8	Left Back Panel	160.0	163	150	167
9	Right Front Fender	152.0	162	152	142
10	Right Front Door	155.3	164	155	147
11	Center Panel Right				
12	Right Rear Door	152.6	176	137	145
13	Right Back Panel	160.0	170	148	162

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Small</p>	<p>Remarks (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/No spare key/No jack and incomplete tools/with reverse camera/with warranty booklet/No seat cover</p>