

General Information

Date & Time: 04, Mar, 2026 15:35

Make	Toyota	Model	Lite Ace
YOM	2023	Odo Meter Reading	47,890
Registration No.	NHJ8805	Chassis No.	MHKU3FE10PK004351
CC	1.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	62.5	59	69	61
2	Boot Lid	103.4	111	100	99
3	Roof	55.6	48	66	51/58
4	Left Front Fender	60.8	61	62	60
5	Left Front Door	61.6	62	64	60
6	Center Panel Left	72.1	79	63	75
7	Left Rear Door				
8	Left Back Panel	128.0	114	159	111
9	Right Front Fender	60.5	70	56	56
10	Right Front Door	64.4	59	62	73
11	Center Panel Right	95.2	82	74	129
12	Right Rear Door				
13	Right Back Panel	143.5	99	243	88

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Floor Mat - Worked - Large / (L) Front Trim - Missing - Yes / (L) Front Trim - Worked - Small / (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes / Dashboard - Worked - Minimal / Rear Seat - Worn - Yes / (R) Front Trim - Worked - Small / Ceiling - Crinkle - Small / Sunvisor, Sunglass Holder - Grime - Medium / Glove Box - Worked - Minimal</p>		<p>Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Corner Panel - Repair Traces - Yes / (L) Front Door, Molding - Scratch - Medium / (L) Side Gate - Scratch & Dent - Medium / Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Cargo Bed Floor - Scratch - Small / (R) Side Gate - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Center Panel - Scratch & Dent - Minimal / (L) Center Panel - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Small / Front Panel - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch & Dent - Minimal / Roof - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Medium / Cab Back Panel - Scratch & Dent - Small</p>	
Frame Evaluation :	B	Functional Evaluation :	A
<p>Remarks Front Floor and Side Member - Traces of Bending, or Marks of Panel Repair ? - Yes</p>		<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate, with inc tools, with spare tire, no spare key, no warranty and manual booklet, issue on head unit.