

## General Information

Date & Time: 02, Mar, 2026 16:34

<b>Make</b>	Toyota	<b>Model</b>	Avanza
<b>YOM</b>	2011	<b>Odo Meter Reading</b>	244,634
<b>Registration No.</b>	TBI409	<b>Chassis No.</b>	MHFM1BE2F8K019367
<b>CC</b>	1.3	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Wagon
<b>Colour</b>	Blue		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	89.7	99	77	92
2	Boot Lid	321.3	325	175	464
3	Roof	75.8	81	61	97/65
4	Left Front Fender	175.3	149	255	122
5	Left Front Door	185.0	224	184	147
6	Center Panel Left				
7	Left Rear Door	92.5	85	96	97
8	Left Back Panel	121.2	135	133	96
9	Right Front Fender	229.0	149	185	353
10	Right Front Door	113.0	105	110	124
11	Center Panel Right				
12	Right Rear Door	95.8	107	100	81
13	Right Back Panel	216.6	208	250	192

## Overall Evaluation :

**E**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

