

General Information

Date & Time: 27, Feb, 2026 18:59

Make	Toyota	Model	Hilux
YOM	2019	Odo Meter Reading	78,703
Registration No.	GAM1206	Chassis No.	MR0GB8DD5K1346614
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.6	121	142	123
2	Boot Lid	107.2	117	105	100
3	Roof	100.3	95	93	101/112
4	Left Front Fender	109.0	107	111	109
5	Left Front Door	106.3	112	106	101
6	Center Panel Left				
7	Left Rear Door	101.7	104	102	99
8	Left Back Panel	163.6	161	163	167
9	Right Front Fender	110.6	104	116	112
10	Right Front Door	100.8	106	102	94
11	Center Panel Right				
12	Right Rear Door	98.3	98	99	99
13	Right Back Panel	102.1	107	97	102

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Ceiling - Grime - Minimal / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Minimal / Rear Seat Head Rest - Partially Missing - Yes / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Rear Trim - Grime - Minimal / (R) Rear Trim - Grime - Minimal</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Side Gate - Scratch & Dent - Medium / Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Minimal / (L) Side Gate - Repair mark - Difference in Color / (L) Side Gate - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch & Dent - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>NO Lto Rear Plate, 1key, no warranty booklet, no spare tire, no jack and tools, scratches on headlights and taillights,battery weak,</p>