

## General Information

Date & Time: 02, Mar, 2026 14:13

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	43,992
<b>Registration No.</b>	FAQ2987	<b>Chassis No.</b>	PA1B18F34P4228712
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.2	97	100	93
2	Boot Lid	103.5	97	113	101
3	Roof	89.2	89	98	83/87
4	Left Front Fender	87.0	90	84	88
5	Left Front Door	87.8	88	85	91
6	Center Panel Left				
7	Left Rear Door	94.0	93	91	98
8	Left Back Panel	98.3	107	95	93
9	Right Front Fender	92.0	90	92	94
10	Right Front Door	88.6	92	87	87
11	Center Panel Right				
12	Right Rear Door	91.2	97	86	90
13	Right Back Panel	94.0	91	92	100

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>B</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (L) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Small / (L) Front Trim - Grime - Small</p>	<p><b>Remarks</b> Bonnet, Headlight - Dent - Small / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>C</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>No Spare Tire. No spare key. No warranty booklet. with seat cover. with Tools. no jack</p>