

General Information

Date & Time: 02, Mar, 2026 14:58

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	19,750
Registration No.	FAR4340	Chassis No.	PA1B18F34R4247800
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.0	105	100	101
2	Boot Lid	107.3	101	115	106
3	Roof	94.1	94	95	94/95
4	Left Front Fender	91.4	87	90	98
5	Left Front Door	94.0	91	91	100
6	Center Panel Left				
7	Left Rear Door	100.6	105	94	103
8	Left Back Panel	96.7	103	95	92
9	Right Front Fender	93.8	96	92	94
10	Right Front Door	99.1	100	99	99
11	Center Panel Right				
12	Right Rear Door	99.0	90	93	114
13	Right Back Panel	103.6	101	100	110

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Medium / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Rear Trim - Grime - Small</p>	<p>Remarks (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Dent - Small / Trunk Hood, Rear Gate - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Dent - Medium / Roof - Rust, Corrosion - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>No spare key. No Spare Tire. No warranty Booklet. No jack with tools. with seat cover</p>