

General Information

Date & Time: 02, Mar, 2026 10:16

Make	Suzuki	Model	Dzire
YOM	2025	Odo Meter Reading	7,727
Registration No.	GBJ8894	Chassis No.	MBHZF63S5SG591422
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.5	94	100	102
2	Boot Lid	82.6	85	85	78
3	Roof	97.5	90	91	102/108
4	Left Front Fender	96.2	90	102	97
5	Left Front Door	91.0	91	88	95
6	Center Panel Left				
7	Left Rear Door	85.6	91	91	75
8	Left Back Panel	88.5	85	87	94
9	Right Front Fender	97.7	106	97	91
10	Right Front Door	96.6	99	91	100
11	Center Panel Right				
12	Right Rear Door	88.8	82	90	95
13	Right Back Panel	93.1	90	103	86

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Medium / Ceiling - Grime - Small</p>	<p>Remarks (L) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>Acting like neutral when in driver or reverse, with spare tire. no warranty booklet. no seat cover. no jack and tools</p>