

General Information

Date & Time: 04, Mar, 2026 10:08

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	5,618
Registration No.	DBQ6543	Chassis No.	MHFAA1BY2R0030418
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.6	103	107	110
2	Boot Lid	96.5	102	100	88
3	Roof	112.5	126	120	101/103
4	Left Front Fender	95.6	98	97	92
5	Left Front Door	113.0	102	115	122
6	Center Panel Left				
7	Left Rear Door	110.0	114	102	114
8	Left Back Panel	106.6	110	103	107
9	Right Front Fender	97.6	96	102	95
10	Right Front Door	110.3	116	115	100
11	Center Panel Right				
12	Right Rear Door	110.3	117	104	110
13	Right Back Panel	110.1	120	96	114

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Small</p>	<p>Remarks Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with 1 spare key/with seat cover /with jack and incomplete tools/with reverse camera/with warranty booklet</p>