

General Information

Date & Time: 03, Mar, 2026 15:55

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	22,784
Registration No.	NGC9585	Chassis No.	PA1B18F3XR427594
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	114	108	110
2	Boot Lid	113.0	112	110	117
3	Roof	98.5	103	100	93/98
4	Left Front Fender	104.0	103	109	100
5	Left Front Door	105.0	102	102	111
6	Center Panel Left				
7	Left Rear Door	109.0	111	107	109
8	Left Back Panel	114.6	127	111	106
9	Right Front Fender	107.6	108	109	106
10	Right Front Door	105.3	101	114	101
11	Center Panel Right				
12	Right Rear Door	99.6	92	96	110
13	Right Back Panel	105.3	100	104	112

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Rear Seat - Grime - Minimal / (R) Front Seat - Worn - Yes / (L) Front Seat - Worn - Yes / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small / Console, Switchs, Vents - Traces of Adhesive Tape - Yes / (R) Rear Trim - Cut, Crack - Minimal</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet and jack, incomplete tools, with spare tire, with LTO plate, scratches on tail light, possible flooding, left cheek light missing,</p>