

General Information

Date & Time: 03, Mar, 2026 13:14

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	43,257
Registration No.	NHS2619	Chassis No.	PA1B18F30R4255943
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.3	125	110	126
2	Boot Lid	116.6	113	119	118
3	Roof	127.5	122	161	113/114
4	Left Front Fender	107.4	99	115	108
5	Left Front Door	109.0	108	106	113
6	Center Panel Left				
7	Left Rear Door	119.0	136	118	103
8	Left Back Panel	121.3	125	124	115
9	Right Front Fender	103.3	103	104	103
10	Right Front Door	108.3	113	109	103
11	Center Panel Right				
12	Right Rear Door	111.3	108	106	120
13	Right Back Panel	118.0	121	108	125

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	D	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Large / (L) Front Seat - Grime - Large / Steering Wheel - Worn, Peel, Crack - Small / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes</p>		<p>Remarks Trunk Hood, Rear Gate - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Medium / (L) Front Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate/with spare tire/No seat cover/with jack and incomplete tools/With reverse camera/with warranty booklet/