

General Information

Date & Time: 03, Mar, 2026 14:54

Make	Toyota	Model	Corolla Altis
YOM	2020	Odo Meter Reading	35,132
Registration No.	NGG9132	Chassis No.	MR2BB3BE7K2001174
CC	1.6	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.3	113	113	111
2	Boot Lid	103.1	103	114	92
3	Roof	120.5	102	123	128/129
4	Left Front Fender	123.3	114	128	128
5	Left Front Door	108.6	122	101	103
6	Center Panel Left				
7	Left Rear Door	103.6	107	104	100
8	Left Back Panel	112.3	105	115	117
9	Right Front Fender	126.3	115	136	128
10	Right Front Door	102.6	104	102	102
11	Center Panel Right				
12	Right Rear Door	99.0	94	100	103
13	Right Back Panel	109.3	115	110	103

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Large / (R) Front Floor Mat - Worked - Large</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Large / (L) Mirror - Scratch - Small / Roof - Scratch - Large / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet/ with spare tire and LTO plate/ with jack and tools/</p>