

General Information

Date & Time: 03, Mar, 2026 14:06

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	22,362
Registration No.	NKG2883	Chassis No.	PA1B18F39R4271848
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.3	101	117	128
2	Boot Lid	112.6	108	110	120
3	Roof	102.6	105	103	108/94
4	Left Front Fender	97.7	99	98	96
5	Left Front Door	109.3	100	107	121
6	Center Panel Left				
7	Left Rear Door	122.0	125	111	130
8	Left Back Panel	116.3	129	117	103
9	Right Front Fender	107.3	117	104	101
10	Right Front Door	98.9	98	101	98
11	Center Panel Right				
12	Right Rear Door	103.0	103	102	104
13	Right Back Panel	103.6	107	102	102

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	E
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Minimal / Rear Seat - Grime - Minimal / Ceiling - Grime - Minimal</p>		<p>Remarks (L) Rear Door - Repair Traces - Yes / Roof - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Medium / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Front Windshield - Scratch, Stone chip - Medium</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate, with spare tire, with jack and inc tools,with manual and warranty booklet, with reverse camera, no spare key, scratches on taillight and headlight, windshield issue,