


General Information

Date & Time: 04, Mar, 2026 12:32

Make	Toyota	Model	Raize
YOM	2023	Odo Meter Reading	23,494
Registration No.	GAQ9764	Chassis No.	MHKAB1BAXPJ046830
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.9	147	61	140
2	Boot Lid	90.3	96	94	81
3	Roof	110.6	99	125	119/100
4	Left Front Fender	154.0	161	152	149
5	Left Front Door	96.3	101	94	95
6	Center Panel Left				
7	Left Rear Door	90.7	94	88	90
8	Left Back Panel	187.6	150	254	159
9	Right Front Fender	141.3	151	146	127
10	Right Front Door	101.7	104	97	104
11	Center Panel Right				
12	Right Rear Door	83.2	83	81	86
13	Right Back Panel	82.8	89	79	81

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Minimal / Carpet - Worn, Scratch, Cut, Crack - Small / (R) Rear Trim - Grime - Small / Rear Seat - Grime - Minimal / Trunk Room - Worn, Scratch, Cut, Crack - Large / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Minimal / Ceiling - Grime - Large / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Crack, Gap - Large / Bonnet, Headlight - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Crack, Gap - Large / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Large / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Roof - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Large / Front Windshield - Damaged - Large / (R) Front Door, Molding - Scratch & Dent - Medium</p>
Frame Evaluation : B	Functional Evaluation : B
<p>Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Without LTO plate/no warranty booklet/no tools and jack/no spare tire/</p>