

## General Information

Date & Time: 03, Mar, 2026 16:44

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	18,732
<b>Registration No.</b>	GBE9033	<b>Chassis No.</b>	PA1B18F39R4267850
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Black		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	112	106	115
2	Boot Lid	106.3	104	105	110
3	Roof	103.6	102	107	106/99
4	Left Front Fender	96.7	98	97	96
5	Left Front Door	109.0	108	110	109
6	Center Panel Left				
7	Left Rear Door	110.0	113	108	109
8	Left Back Panel	119.0	133	111	113
9	Right Front Fender	198.6	221	213	162
10	Right Front Door	112.6	116	120	102
11	Center Panel Right				
12	Right Rear Door	115.3	115	111	120
13	Right Back Panel	115.6	113	110	124

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

