

General Information

Date & Time: 03, Mar, 2026 16:23

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	6,470
Registration No.	GBK1495	Chassis No.	MHKAA1BC1SJ037589
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.6	118	123	124
2	Boot Lid	111.6	116	113	106
3	Roof	102.5	108	102	103/97
4	Left Front Fender	105.0	107	108	100
5	Left Front Door	114.6	121	112	111
6	Center Panel Left				
7	Left Rear Door	114.6	122	106	116
8	Left Back Panel	111.6	112	121	102
9	Right Front Fender	102.8	96	103	109
10	Right Front Door	111.0	115	112	106
11	Center Panel Right				
12	Right Rear Door	113.6	113	109	119
13	Right Back Panel	108.3	109	108	108

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Grime - Large / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Medium / Mat Other - Grime - Large / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>Gap at front bumper. With warranty booklet, spare tire, jack and seat cover. Without tools. 2 keys. With LTO plate.</p>