

General Information

Date & Time: 03, Mar, 2026 14:34

Make	Toyota	Model	Wigo
YOM	2024	Odo Meter Reading	23,349
Registration No.	FAQ4782	Chassis No.	MHKAA1BC7PJ009013
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.4	102	100	99
2	Boot Lid	84.7	83	93	78
3	Roof	77.2	79	88	73/69
4	Left Front Fender	93.9	85	96	101
5	Left Front Door	102.2	97	99	111
6	Center Panel Left				
7	Left Rear Door	91.2	100	84	90
8	Left Back Panel	83.5	84	84	83
9	Right Front Fender	92.3	100	95	83
10	Right Front Door	98.3	102	98	95
11	Center Panel Right				
12	Right Rear Door	90.1	87	85	99
13	Right Back Panel	83.4	86	83	81

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Small / (R) Front Trim - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>maintenance lamp on. With spare tire. no spare key. no seat cover. slight engine noise. no warranty booklet. no spoiler all doors</p>