

General Information

Date & Time: 03, Feb, 2025 18:47

Make	Toyota	Model	Vios
YOM	2023	Mileage	28,211
Registration No.	NHI7601	Chassis No.	PA1B18F34P4211019
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.3	118	109	119
2	Boot Lid	138.6	145	116	155
3	Roof	112.5	114	103	117/116
4	Left Front Fender	98.3	101	99	96
5	Left Front Door	143.0	148	140	141
6	Center Panel Left				
7	Left Rear Door	105.7	117	104	96
8	Left Back Panel	101.6	102	101	102
9	Right Front Fender	131.6	103	138	154
10	Right Front Door	91.7	90	88	97
11	Center Panel Right				
12	Right Rear Door	101.2	95	104	105
13	Right Back Panel	105.6	108	103	106

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / Ceiling - Crinkle - Small	Remarks (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with spare tire. without warranty booklet, jack and tools. with LTO plate.