


General Information

Date & Time: 04, Feb, 2025 14:48

Make	Toyota	Model	Vios
YOM	2023	Mileage	26,843
Registration No.	DBI6040	Chassis No.	PA1B18F30P4215357
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.3	105	95	107
2	Boot Lid	100.1	94	103	103
3	Roof	97.5	101	89	99/102
4	Left Front Fender	89.3	91	92	85
5	Left Front Door	88.8	87	86	94
6	Center Panel Left				
7	Left Rear Door	100.2	107	99	95
8	Left Back Panel	96.0	96	98	94
9	Right Front Fender	85.7	84	88	86
10	Right Front Door	90.8	92	87	94
11	Center Panel Right				
12	Right Rear Door	98.4	93	93	109
13	Right Back Panel	88.8	87	89	91

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Rear Seat - Grime - Small / Mat Other - Grime - Small / (R) Front Seat - Grime - Small / Ceiling - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Dent - Minimal / Bonnet, Headlight - Scratch & Dent - Minimal / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / Roof - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Remote Key & Smart entry - Issue - Yes / Reverse Camera - N/A - Yes

Inspector Notes
with warranty booklet and spare tire. without jack and tools. with LTO plate. car key button partially missing.